

THESE WIRES TO THE SPEEDOMETER SENSOR
Orange, +12 Volt sensor power
Black, Ground
Green, Signal
Connector to odometer
and trip meter reset switch.
WIRES TO THE MAIN WIRE HARNESS
Red, +12 volt Battery
Black, Ground