ZPN 782190 TGS (Throttle Grip Sensor) 2008-2015

IMPORTANT: Whenever a new TGS (Throttle Grip Sensor, the official name for the Throttle-By-Wire assembly) is installed, idle speed must be reset. The ECM uses the first four ignition cycles to establish the optimum idle speed. If the procedure is not performed, initial performance problems may result or DTC (Diagnostic Trouble Codes) may come up.

• Place the engine run/stop switch in the RUN position.

• Turn the ignition/light keyswitch to IGNITION and then, after at least 3 seconds back to OFF. Repeat this three time (so four times in total)

